

**ID**    **1**

**Category:**

**Stairs**

**Location:**

**NE corner of State Office Building, looking south**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Stairs down to courtyard area

Survey Date    06/01/00



**ID**    **2**


**Category:**                    **Stairs**  
**Location:**                   **East of State Office Building, looking east**

*Satisfactory:*                ☐  
*Damaged:*                   ☒  
*Condition Code:*           ST

*Condition Description:*   Significant Staining, needs cleaning;  
   may indicate rusted connector

*Comments:*                   Rusted areas on edges of steps

Survey Date    06/01/00



**ID**    **3**

**Category:**

**Stairs**

**Location:**

**East of State Office Building; looking north**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Stairs to Middle East parking area.

Survey Date    06/01/00



**ID**    **4**

**Category:**

**Stairs**

**Location:**

**East of State Office Building, looking east**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Stairs to Middle East parking area.

Survey Date    06/01/00





ID 5

**Category:**

**Stairs**

**Location:**

**East of Cafeteria, to Middle East parking lot**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Ramp not handicap accessible per sign located at top of ramp.

Survey Date 03/24/00



ID 6

**Category:** Stairs  
**Location:** Southeast of State Office Building; looking north  
**Satisfactory:** ☒  
**Damaged:** ☐  
**Condition Code:**  
**Condition Description:**  
**Comments:**

Survey Date 06/01/00



ID 7

**Category:**

**Stairs**

**Location:**

**State Capitol, east entrance**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date 06/01/00



ID 8

**Category:**

**Stairs**

**Location:**

**State Capitol, front steps**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date 06/01/00



**ID**    **10**

**Category:**

**Stairs**

**Location:**

**State Capitol, front stairs**

*Satisfactory:*

☐

*Damaged:*

☒

*Condition Code:*

CO

*Condition Description:*

Cracked, spalled, damaged concrete,  
needs repair or replacement

*Comments:*

Survey Date    06/01/00





**ID**    **11**

**Category:**

**Stairs**

**Location:**

**State Capitol, front steps**

*Satisfactory:*

☐

*Damaged:*

☒

*Condition Code:*

CO

*Condition Description:* Cracked, spalled, damaged concrete,  
needs repair or replacement

*Comments:*

Survey Date    03/23/00



<b>ID</b>	<b>12</b>
-----------	-----------

<b>Category:</b>	<b>Stairs</b>
<b>Location:</b>	<b>State Capitol, front lawn stairs, looking west</b>
<i>Satisfactory:</i>	<input checked="" type="checkbox"/>
<i>Damaged:</i>	<input type="checkbox"/>
<i>Condition Code:</i>	
<i>Condition Description:</i>	
<i>Comments:</i>	


Survey Date 06/01/00



ID 13

**Category:** Stairs  
**Location:** Mormon Battalion Monument, SE corner of site  
**Satisfactory:** ☐  
**Damaged:** ☒  
**Condition Code:** CO  
**Condition Description:** Cracked, spalled, damaged concrete, needs repair or replacement  
**Comments:**

Survey Date 03/23/00



**ID**    **14**

**Category:**

**Stairs**

**Location:**

**Southwest corner of State Capitol lawn**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date    06/01/00



ID 15

**Category:**

### Stair feature

***Location:***

### West entrance to State Capitol

*Satisfactory:*

5

*Damaged:*

☒

*Condition Code:*

CO

*Condition Description:*

Cracked, spalled, damaged concrete,  
needs repair or replacement

*Comments:*

See next photo for side view.

Survey Date 03/23/00





<b>ID</b>	<b>16</b>
-----------	-----------

<b>Category:</b>	<b>Stair feature</b>
<b>Location:</b>	<b>West entrance at Columbus Street</b>
<i>Satisfactory:</i>	<input type="checkbox"/>
<i>Damaged:</i>	<input checked="" type="checkbox"/>
<i>Condition Code:</i>	CO
<i>Condition Description:</i>	Cracked, spalled, damaged concrete, needs repair or replacement
<i>Comments:</i>	

Survey Date 06/01/00



**ID** 17

**Category:**

**Stair feature**

**Location:**

**West entrance at Columbus Street**

*Satisfactory:*

☐

*Damaged:*

☒

*Condition Code:*

CO

*Condition Description:* Cracked, spalled, damaged concrete,  
needs repair or replacement

*Comments:*

Survey Date 03/23/00



ID 18

**Category:** Stair feature  
**Location:** West entrance at Columbus Street

**Location:** West entrance at Columbus Street

☐☒

CO

*Condition Description:* Cracked, spalled, damaged concrete,  
needs repair or replacement

*Comments:*

Comments:

Survey Date 03/23/00



**ID**    **19**

**Category:**

**Stairs**

**Location:**

**West entrance along Columbus Street**

*Satisfactory:*

☐

*Damaged:*

☒

*Condition Code:*

CO

*Condition Description:* Cracked, spalled, damaged concrete,  
needs repair or replacement

*Comments:*

Survey Date    06/01/00



**ID**    **20**

**Category:**

**Stairs**

**Location:**

**Vietnam Memorial**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date   06/01/00





ID 21

**Category:** Stairs  
**Location:** State Capitol, west entrance

*Satisfactory:* ☐

*Damaged:* ☒

*Condition Code:* CO

*Condition Description:* Cracked, spalled, damaged concrete,  
needs repair or replacement

*Comments:*

Survey Date 06/01/00



**ID**    **22**

**Category:**                    **Stairs**  
**Location:**                   **State Capitol, west entrance**

*Satisfactory:*                ☐

*Damaged:*                   ☒

*Condition Code:*           **O**

*Condition Description:*   **Other (describe)**

*Comments:*                   Uneven transistion from steps to Capitol;  
pedestrian traffic must step across gutter and  
patched pavement to reach stairs.

Survey Date   06/01/00



ID 23

**Category:**

**Stairs**

**Location:**

**State Capitol, west entrance**

*Satisfactory:*



*Damaged:*




*Condition Code:*

*Condition Description:*

*Comments:*

Edges of steps show a few minor chips/spalling on the concrete.

Survey Date 06/01/00



**ID**    **24**

**Category:**

**Sidewalks**

**Location:**

**West of Plaza area**

*Satisfactory:*



*Damaged:*




*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date    06/01/00



**ID**    **26**

**Category:**

**Sidewalk**

**Location:**

**Plaza between State Office Building and  
Garage**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

New concrete.

Survey Date    06/01/00





ID 27

**Category:** Sidewalks  
**Location:** West of State Office Building  
  
*Satisfactory:* ☒  
*Damaged:* ☐  
*Condition Code:*  
  
*Condition Description:*  
  
*Comments:* New concrete.

Survey Date 06/01/00



ID 28

**Category:**

**Sidewalks**

**Location:**

**Northwest corner of State Office Building**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Ramp to equipment room.

Survey Date 06/01/00



ID 29

**Category:** Sidewalk  
**Location:** Northwest Corner of State Office Building

*Satisfactory:* ☒

*Damaged:* ☐

*Condition Code:*

*Condition Description:*

*Comments:* Ramp in good condition also.

Survey Date 06/01/00



ID 30

**Category:**

**Sidewalks**

**Location:**

**West of Data Processing Center**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

New concrete, handicap accessible.

Survey Date 06/01/00



**ID**    **31**

**Category:**

**Sidewalk**

**Location:**

**Archves Building, east of and adjacent to**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Large drop at entrance to ramp is difficult to see on the asphalt.

Survey Date    06/01/00





**ID**    **32**

**Category:**

**Sidewalks**

**Location:**

**Corner of 500 North & Columbus St,  
looking south**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date   06/01/00



**ID**    **33**

**Category:**

**Sidewalks**

**Location:**

**Corner of 500 North and Columbus St,  
looking east**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date    06/01/00



**ID**    **34**

**Category:**

**Sidewalk**

**Location:**

**500 North behind Archives Building**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

A few cracks from settling. No handicap ramp,  
no handicap access per sign.

Survey Date    06/01/00



**ID**    **35**

**Category:**

**Sidewalks**

**Location:**

**500 North, adjacent to Archives Building**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Good condition, steep curb. No handicap access along this sidewalk.

Survey Date    06/01/00



**ID**    **36**

**Category:**                      **Sidewalk**  
**Location:**                      **500 North, east of Greenhouse Facility**  
  
*Satisfactory:*                      ☒  
*Damaged:*                        ☐  
*Condition Code:*  
  
*Condition Description:*  
  
*Comments:*                      Steep sidewalk.

Survey Date    06/01/00





**ID**    **37**

**Category:**

**Sidewalks**

**Location:**

**500 North, looking toward East Capitol Blvd.**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date    06/01/00



**ID**    **38**

**Category:**

**Sidewalks**

**Location:**

**500 North at East Capitol Blvd.**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

No handicap ramp. End of sidewalk - none along East Capitol.

Survey Date    03/24/00



**ID**    **39**

**Category:**

**Sidewalks**

**Location:**

**Northeast parking area, east of State Office Bldg.**

*Satisfactory:*

☐

*Damaged:*

☐

*Condition Code:*

O

*Condition Description:* Other (describe)

*Comments:*

Sidewalk obstructed by large antennae. Cars also extend onto sidewalk as there is no curb to keep cars back.

Survey Date    03/24/00



**ID**    **40**

**Category:**

**Sidewalks**

**Location:**

**Adjacent to State Office Building, NE  
courtyard**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date    06/01/00



**ID**    **41**

**Category:**

**Sidewalks**

**Location:**

**East exit of State Office Bldg, looking south**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date    06/01/00





ID 42

Survey Date 06/01/00

**Category:**

## Sidewalks

***Location:***

**NE courtyard of State Office Building**

*Satisfactory:*

☐

*Damaged:*

☒

*Condition Code:*

CO

*Condition Description:*

Cracked, spalled, damaged concrete,  
needs repair or replacement

*Comments:*

Uneven patchwork, severe cracking and erosion in corner.



ID 43

**Category:**

**Sidewalk**

**Location:**

**Plaza between Cafeteria & State Bldg,  
looking west**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Note that grout between bricks was missing in some locations.

Survey Date 06/01/00



**ID**    **44**

Survey Date    06/01/00

**Category:**

**Sidewalk**

**Location:**

**SE corner of State Office Bldg., facing  
cafeteria**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Sloped access from parking to allow handicap  
access to sidewalk.



ID 45

**Category:**

**Sidewalk**

**Location:**

**East of Cafeteria, looking towards Capitol**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date 06/01/00





ID 46

**Category:**

**Sidewalk**

**Location:**

**NE of Capitol, looking west, cafeteria on right**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Handicap access point behind Capitol.

Survey Date 06/01/00





ID 52

**Category:**

**Sidewalks**

**Location:**

**Front lawn of Capitol, upper elev, looking south**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date 06/01/00



**ID**    **53**

**Category:**

**Sidewalks**

**Location:**

**Front lawn of Capitol, lower elev, looking south**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date    06/01/00



ID 47

**Category:**

**Sidewalk**

**Location:**

**East of Capitol, between east parking areas**

*Satisfactory:*



*Damaged:*




*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date 06/01/00



ID 48

**Category:**

**Sidewalks**

**Location:**

**East entrance to Capitol**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

New concrete, handicap access ramp.

Survey Date 06/01/00



ID 49

**Category:**

**Sidewalks**

**Location:**

**East access to parking garage behind Capitol**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date 06/01/00





ID 50

**Category:**

**Sidewalks**

**Location:**

**Bus parking east of Capitol**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date 06/01/00





**ID**    **51**

**Category:**

**Sidewalks**

**Location:**

**SE corner of Capitol, looking across loop parking**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date   06/01/00



**ID**    **54**

**Category:**

**Sidewalks**

**Location:**

**SE corner of site, across from Council Hall**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Condition good. Note access across 300 North (pass through to the right ahead of vehicle) has no straight path to sidewalk or ramp (in foreground of photo).

Survey Date    06/01/00



**ID**    **55**

**Category:**

**Sidewalks**

**Location:**

**South entry to loop parking along 300 North**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date    06/01/00



**ID**    **56**

**Category:**

**Sidewalks**

**Location:**

**Entrance to loop parking, looking west  
along 300N**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date    06/01/00



ID 57

**Category:**

**Sidewalks**

**Location:**

**Entrance to SW parking, looking west on  
300 North**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Sidewalk condition good. Entrance to parking  
area in poor condition due to drainage problems.

Survey Date 06/01/00






**ID**    **58**

**Category:**                      **Sidewalks**  
**Location:**                      **SW corner of site, looking west along 300 North**  
**Satisfactory:**                      ☒  
**Damaged:**                        ☐  
**Condition Code:**  
**Condition Description:**  
**Comments:**                      Some minimal settling.

Survey Date    06/01/00



**ID**    **59**

Survey Date    06/01/00

**Category:**                      **Sidewalks**  
**Location:**                      **SW corner of site, looking north on  
Columbus St.**  
  
*Satisfactory:*                      ☒  
*Damaged:*                        ☐  
  
*Condition Code:*  
  
*Condition Description:*  
  
  
*Comments:*                      Some minimal settling.



**ID**    **60**

**Category:**

**Sidewalks**

**Location:**

**SW corner of site, monument area**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date    06/01/00



**ID**    **61**

**Category:**                **Sidewalks**  
**Location:**                **SW parking area**

*Satisfactory:*            ☒

*Damaged:*                ☐

*Condition Code:*

*Condition Description:*

*Comments:*              Handicap access to monument areas

Survey Date    06/01/00



ID 62

**Category:**

## Sidewalks

***Location:***

**West pedest. entrance to Capitol, at  
Vietnam Mem.**

*Satisfactory:*

9

*Damaged:*

☒

*Condition Code:*

CO

*Condition Description:*

Cracked, spalled, damaged concrete,  
needs repair or replacement

*Comments:*

Some settling, large cracks

Survey Date 06/01/00





**ID**    **63**

**Category:**

**Sidewalks**

**Location:**

**Vietnam Memorial Entrance**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Handicap access ramp to monument

Survey Date    06/01/00



**ID**    **64**

**Category:**

**Sidewalks**

**Location:**

**Interior walkway at Vietnam Memorial**

*Satisfactory:*

☐

*Damaged:*

☒

*Condition Code:*

O

*Condition Description:* Other (describe)

*Comments:*

Cracked tiles, loose chips, need repair or replacement

Survey Date   03/23/00



**ID**    **65**

**Category:**

**Sidewalks**

**Location:**

**West entrance to Capitol, south along  
parking loop**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Some minimal settling

Survey Date    06/01/00



**ID**    **66**

**Category:**

**Sidewalks**

**Location:**

**SE corner of Capitol Bldg, looking south**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Survey Date    06/01/00



**ID**    **67**

Survey Date    06/01/00

**Category:**                **Sidewalks**

**Location:**                **West entrance at Columbus Street, looking north**

*Satisfactory:*            ☐

*Damaged:*                ☒

*Condition Code:*        CO

*Condition Description:*    Cracked, spalled, damaged concrete, needs repair or replacement

*Comments:*                Uneven surface for wheelchairs, poor condition for pedestrian entrance to Capitol.





**ID**    **68**

**Category:**

**Sidewalks**

**Location:**

**West entrance at Columbus, facing Capitol**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Some settling, different color grout unappealing for large entrance way.

Survey Date    06/01/00



**ID**    **69**

**Category:**                      **Sidewalks**  
**Location:**                      **West pedestrian entrance at Columbus Street**  
  
*Satisfactory:*                      ☐  
*Damaged:*                        ☒  
  
*Condition Code:*                CO  
  
*Condition Description:*      Cracked, spalled, damaged concrete, needs repair or replacement  
  
*Comments:*                      Severe cracking, unlevel surface

Survey Date    03/23/00



**ID**    **70**

**Category:**

**Sidewalks**

**Location:**

**West handicap entrance at Apricot Street**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Some cracking, generally smooth for handicap access.

Survey Date    03/23/00



**ID**    **73**

**Category:**

**Sidewalks**

**Location:**

**West entrance to NW parking area**

*Satisfactory:*



*Damaged:*



*Condition Code:*

*Condition Description:*

*Comments:*

Sidewalk good condition. Note no handicap ramp on either end of sidewalk.

Survey Date    03/23/00

